



GARY R. HERBERT
Governor
SPENCER J. COX
Lieutenant Governor

State of Utah


DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Minerals Inspection Report

Reviewed 


Report Date: 07/15/2014

Mine Name: Barneys Canyon Mine	Permit Number: M/035/0009	Mine Status: Active
Operator Name: Rio Tinto - Kennecott Utah Copper	Inspection Date: August 21, 2013	Permit Fees: Paid
Inspector(s): L Heppler, A Abate, T Nicolaysen	Inspection Time: 11:00 AM	Bond Amount: \$3,873,446
Attendee(s): T Lindsay, T Heaton	Weather: Sunny, Dry	Bond Escalation: 06/22/2014
Inspection Purpose: Routine annual inspection		Prior Inspection: May 10, 2012

Conclusions and Recommendations

The Barneys, Melco, North BC South and South BC South pits have been reclaimed, along with most haul roads and dumps. OGM to continue annual inspections and monitor the site when in the area.

Elements of Inspection	Evaluated & Commented	Enforcement
1. <i>Permits, Revisions, Transfer, Bonds</i> Permit fee is up to date, reclamation bond up to date at the time of inspection.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. <i>Public Safety (shafts, adits, trash, signs, highwalls)</i> Mine site is accessed through a paved road and a full time manned secure entrance.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. <i>Protection of Drainages/Erosion Control</i> No erosional problems were noted during inspection.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. <i>Deleterious Material</i> All deleterious material are properly stored and contained	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. <i>Roads (maintenance, surfacing, dust control, safety)</i> Roads were well maintained and in good condition with water for dust suppression	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. <i>Reclamation</i> Concurrent reclamation at the site at the time of inspection includes the demolition of the truck shop.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. <i>Backfilling/Grading (trenches, pits, roads, highwalls, shafts)</i> Highwalls reclaimed per OGM, dumps have been recontoured, topsoiled and seeded	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. <i>Soils</i> No soil stockpiles are noted at the time of inspection.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. <i>Revegetation</i> Revegetation is doing well - see attached photos	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. <i>Other</i> This line is intentionally left blank	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: 

CC: Chris Kaiser - Kennecott

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M035-SaltLake/M0350009-BarneysCyn/Inspections/INSP-08212013.pdf



Reclaimed Pit



Reclaimed Pit



Reclaimed Pit



Revegetation has been reestablished